

***** MATERIAL SAFETY DATA SHEET *****

BLUE MAX

CONTROL MEASURES

RESPIRATORY PROTECTION: No special protection required if used in normal situations.

VENTILATION: General room ventilation is good.

PROTECTIVE GLOVES: Rubber gloves are recommended.

EYE PROTECTION: Glasses with splash shields, goggles or face shield to prevent eye contact during normal use is recommended.

OTHER PROTECTIVE MEASURES: Good personal hygiene practices. Clean up contaminated equipment and clothing before reuse.

WORK HYGIENIC PRACTICES: Keep off the skin & out of reach of children.

FOR ADDITIONAL INFORMATION

CONTACT: Technical Director, Sunbelt Laboratories, during business hours, central time; (281) 261-4747.

— DISTRIBUTED BY —
NATIONAL AMERICAN SALES
504-447-1434
800-821-3732 (LA)